

SAF® Trailer Axle Production

Production Change Notification - Tire Inflation Prep

Effective: December 1, 2022

Attention

SAF-HOLLAND is implementing a production change on all new SAF® trailer axles produced on or after 12/1/2022. This change will include the addition of a single tire inflation tapped and plugged hole for disc and drum braked axles. This change will be seen on all SAF® trailer suspension axles listed below.


- CBX Fixed Frame Suspensions
- CBX Sliding Suspensions
- CBXA Fixed Frame Suspensions
- CBXA Sliding Suspensions
- CBX/CBXA Replacement Beam/Axle Assemblies
- DLX Fixed Frame Suspensions
- ULX Sliding Suspensions

This change will allow customers to more easily retrofit their axles with tire inflation systems like SAF® Tire Pilot Plus™ and will not change fit, form or function. To use, remove the plug and install tire inflation system per manufacturer's instructions. This change will not affect the current warranty.

If you have any questions or require additional product assistance, please contact your account manager or SAF-HOLLAND Customer Service at 1.800.876.3929.


Parallel Spindle Axles Produced After Dec. 1, 2022

TIRE INFLATION PREP HOLE
TAPPED WITH PLUG



Taper Spindle Axles Produced After Dec. 1, 2022

TIRE INFLATION PREP HOLE
TAPPED WITH PLUG



Axles Produced After Dec. 1

