

Service Bulletin

Integral Disc Brake

Wheel and Valve Stem Clearance Notification

May 2010


Careful attention must be given to the selection of the wheel and air valve stems to be sure they are compatible with Knorr Disc Brake Calipers used on SAF Disc Brake Axles.

CAUTION

Failure to provide adequate clearance between the disc brake caliper and the valve stem may cause the valve stem to shear off resulting in loss of tire pressure and/or additional component damage which, if not avoided, may result in minor to moderate injury.

IMPORTANT: A minimum of .25" (6mm) of clearance should be allowed between the disc brake caliper and the valve stem (**Figure 1**). Only rim and valve stem sizes approved by the trailer manufacturer to be compatible with Knorr Disc Brake.

Figure 1





From fifth wheel rebuild kits to suspension bushing repair kits, SAF-HOLLAND Original Parts are the same quality components used in the original component assembly.

SAF-HOLLAND Original Parts are tested and designed to provide maximum performance and durability. Will-fits, look-alikes or, worse yet, counterfeit parts will only limit the performance potential and could possibly void SAF-HOLLAND's warranty. Always be sure to spec

SAF-HOLLAND Original Parts when servicing your SAF-HOLLAND product.

SAF-HOLLAND USA • 888.396.6501 • Fax 800.356.3929
www.safholland.us

SAF-HOLLAND CANADA • 519.537.3494 • Fax 800.565.7753
WESTERN CANADA • 604.574.7491 • Fax 604.574.0244
www.safholland.ca

SAF-HOLLAND MEXICO • 52.1.55.545668641 • Fax 52.55.58162230
www.safholland.com.mx

info@safholland.com